

## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY SUPERFUND SITE STRATEGY RECOMMENDATION - REGION 06



Site Name: Section 27 Mine - NM0026	··	CERCLIS ID#: N/A
Alias Site Name: United Nuclear		
Address: Latitude 35 degrees 24'39.14" Longitu	de 107 degrees 46'41.02"	·
City/County or Parish/State/Zip: McKinley	County, New Mexico	
Report Type: Pre-CERCLIS Screening	Date: 05/23/12	Author: NMED
RECOMMENDATION:		
1. No Further Remedial Action Planned     Under Superfund (NFRAP)	☐ 2. Further Invest☐ PA☐ SI☐ ESI☐ Other:	igation Needed Under Superfund  HRS Priority: High RI/FS Low RA
<ul><li>□ 3. Action Deferred to: □ RCRA □ NR</li><li>☑ 4. Site Being Addressed Under the State Vol</li></ul>	C BLM	
NOTIFY AUTHORITY:		
Removal RCRA TSC Remedial State/Tribe NPD CERCLA Federal UIC Enforcement Facility	DES 🔲 NRC	SMCRA Resource Trustee: Other:
SEND SSSR COPIES TO: 6SF-AC	☐ 6WQ-SP ☐ ATSDR	
DISCUSSION:		
The New Mexico Environment Department (NM screen for the Section 27 Mine site. The mine op Initial reclamation of the mine occurred in the lat unreclaimed.	perated as a wet mine, with pro-	duction of uranium from 1967 to 1980.
Mine reclamation is being required pursuant to the discharge of mine water and solution mining is be Commission regulations.		
NMED recommended that no further action be ta activities pursuant to New Mexico regulations. E		
	•	11444

APPROVALS:

Report Reviewed by: Lisa Marie Price (Site Assessment Manager)

Disposition Approved by: John Meyer (Section Chief 6SF-TR)

Signature: Lisa Marie Price Date: 5/25/12

Signature: Date: 5/29/12